

## Mid cycle Report to Oregon Public Utility Commission on facility inspections

OAR 860-024-011(1)(b)(A)(ii)

From: Sanjeev King P.E., Electric Engineering Manager  
Springfield Utility Board  
1001 Main Street  
Springfield, OR 97477  
541.736.2331  
[sanjeevk@subutil.com](mailto:sanjeevk@subutil.com)

**This is a summary of the facilities inspection activity for Springfield Utility Board  
For the calendar years 2008 through 2012**

Year	Number	Percentage
2008	884	17.7%
2009	1270	25.4%
2010	0	0.0%
2011	0	0.0%
2012	1075	11.9%
totals	1075	<b>11.9%</b>

Number refers to number of poles  
that were inspected during that calendar year.

### **Plan to catch up to 10% per year for 10 year cycle**

Year	Number	Percentage
2013	1174	13.0%
2014	1137	12.6%
2015	1035	11.5%
2016	1091	12.1%
2017	1048	11.6%
2018	1092	12.1%
2019	1108	12.3%
2020	263	2.9%

totals	7948	88.1%
for the 10 year cycle, total	9023	100.0%