

Mid cycle Report to Oregon Public Utility Commission on facility inspections

OAR 860-024-011(1)(b)(A)(i)

From: LeeAnne Pearson; pearsonl@cuaccess.net; 503-630-8998
Cascade Utilities dba Reliance Connects
PO Box 189, Estacada OR 97023

**This is a summary of the facilities inspection activity for
Cascade Utilities dba Reliance Connects
For the calendar years 2008 through 2012**

Year	Number	Percentage
2008	0	0.0%
2009	98	31.2%
2010	65	20.7%
2011	15	4.8%
2012	26	8.3%
totals	204	65.0%

Number refers to number of poles
that were inspected during that calendar year.