

Mid cycle Report to Oregon Public Utility Commission on facility inspections

OAR 860-024-011(1)(b)(A)(i)

From: Molalla Telephone Company
dba Molalla Communications
211 Robbins Street
PO Box 360
Molalla, OR 97038

This is a summary of the facilities inspection activity for Molalla Communications for the calendar years 2008 through 2012

Year	Number	Percentage
2008	5	100%
2009	5	100%
2010	5	100%
2011	5	100%
2012	5	100%
Totals	25	100%

*Number refers to number of poles that were inspected during that calendar year.

Molalla Communications has not authorized any operators or granted access to our pole infrastructure.